



Jeep

Turin, 29th February 2012

CAMPAIGN 5625 - Service Campaign

**Model: Fiat Ducato with 2.3 JTD 130 HP and 150 HP Euro 5 engine
- engine control unit**

On a batch of Fiat Ducato vehicles with 2.3 JTD 130 HP and 150 HP Euro 5 engine whose chassis numbers range between 1900437 and 2177367, the engine control unit software must be updated to prevent the switching-on of the engine failure warning light and possible power loss of the same engine.

Therefore, it is compulsory to make a pre-delivery intervention on vehicles still in stock. For vehicles which have already been delivered, customers must be contacted by phone, implementing the cycle described in Attachment (Annex 1) to upgrade all vehicles.

Annex





CAMPAIGN

Service Campaign

5625



COMPONENT:	Engine control unit			
PROBLEM:	Non-compliance			
VERSION:	Fiat Professional Ducato 2.3 JTD			
CONCERNED VEHICLES:	All vehicles with chassis number listed in SIGI. (Chassis ranging between 1900437 and 2177367)			
	Vehicles assigned to you: consult your PC for the chassis numbers involved in the campaign.			
TECHNICAL CAUSE:	Production process			
RELEASE NO.:	0			
MATERIAL:	Description:	Part No.:	Q.ty:	
SPECIAL TOOLS:	- Diagnosis equipment			
EPLUS ORDER UPLOADING METHOD:	-			
REMUNERATION:	Cost:	Campaign:	Operation:	Time:
MANPOWER AND MATERIAL:	A01	5625	A	0.30
MISCELLANEOUS (MAIL, ETC.):	A10	5625	-	-
SOLUTION IN PRODUCTION:	Adoption of compliant software			
NETWORK INTERVENTION IDENTIFICATION:	A spot of white paint on fuse box			
	A pre-delivery intervention must be compulsorily made on vehicles still in stock. For vehicles which have already been delivered, customers must be contacted by phone to upgrade all vehicles.			

OPERATING CYCLE

Engine control unit flashing

Diagnosis equipment updated with release 8.20.10 or following.

Connect the diagnosis equipment to the ExaminerWeb and download the release 9.01.0 to update the software for:

FIAT PROFESSIONAL DUCATO FL (250) 2.3 JTD 110 HP - JUDDERING AT LOW ENGINE TEMPERATURE - CAMPAIGN NO. 5625 ERROR P0238 (TURBOCHARGER PRESSURE)
Marelli Diesel Injection 8F3 CF5/EOBD (EP 2.3 JTD engine)

FIAT PROFESSIONAL DUCATO FL (250) 2.3 JTD 130 HP - JUDDERING AT LOW ENGINE TEMPERATURE - CAMPAIGN NO. 5625 ERROR P0238 (TURBOCHARGER PRESSURE)
Marelli Diesel Injection 8F3 CF5/EOBD (EP 2.3 JTD engine)

FIAT PROFESSIONAL DUCATO FL (250) 2.3 JTD 130 HP Stop&Start - JUDDERING AT LOW ENGINE TEMPERATURE - CAMPAIGN NO. 5625 ERROR P0238 (TURBOCHARGER PRESSURE)
Marelli Diesel Injection 8F3 CF5/EOBD (EP 2.3 JTD engine)

FIAT PROFESSIONAL DUCATO FL (250) 2.3 JTD 150 HP - JUDDERING AT LOW ENGINE TEMPERATURE - CAMPAIGN NO. 5625 ERROR P0238 (TURBOCHARGER PRESSURE)
Marelli Diesel Injection 8F3 CF5/EOBD (EP 2.3 JTD engine)

FIAT PROFESSIONAL DUCATO FL (250) 2.3 JTD 150 HP - Stop&Start - JUDDERING AT LOW ENGINE TEMPERATURE - CAMPAIGN NO. 5625 ERROR P0238 (TURBOCHARGER PRESSURE)
Marelli Diesel Injection 8F3 CF5/EOBD (EP 2.3 JTD engine)

Disposal of removed parts:

Removed part return required?: **NO**