



Turin, 25th February 2013

CAMPAIGN 5714 - Service Campaign
Model: Fiat Ducato mot. 2.3 JTD 130 HP
- engine management control unit

On 13 Fiat Ducato vehicles with 2.3 JTD 130 HP engine, whose chassis are listed in Attachment (Annex 1) and range between 2380832 and 2381624, the engine management control unit must be replaced due to non-conformity.



Annexes



Jeep



Annex 1

**Model: Fiat Ducato mot. 2.3 JTD 130 HP
- engine management control unit**

Model	Frame	Market
250	2381209	GERMANY
250	2381285	GERMANY
250	2381304	GERMANY
250	2380914	GERMANY
250	2381296	GERMANY
250	2381317	GERMANY
250	2381607	GERMANY
250	2381374	GERMANY
250	2381177	GERMANY
250	2381085	GERMANY
251	2381624	POLAND
251	2380832	RUMANIA
251	2381096	RUMANIA



CAMPAIGN

Service Campaign

5714



COMPONENT:	Engine management control unit		
FAULT:	Non-compliance		
VERSION:	Fiat Ducato (250) mot. 2.3 JTD 130 HP		
CONCERNED VEHICLES:	All vehicles with chassis numbers listed in SIGI. (Chassis numbers ranging between 2380832 and 2381624)		
	Vehicles assigned to you: consult your PC for the chassis numbers involved in the campaign.		
TECHNICAL CAUSE:	Production process		
RELEASE NO.:	0		
MATERIAL:	Description:	Part No.:	Q.ty:
	Engine management control unit: MJD 8F3	55246589	1
SPECIAL TOOLS:	-		
EPLUS ORDER UPLOADING METHOD:	-		
REMUNERATION:	Cost:	Campaign:	Operation:
MANPOWER AND MATERIAL:	A01	5714	A
MISCELLANEOUS (MAIL, ETC.):	A10	5714	-
SOLUTION IN PRODUCTION:	The fitting of complying parts is guaranteed		
NETWORK INTERVENTION IDENTIFICATION:	A spot of white paint on fuse box		

It is compulsory to make a pre-delivery intervention on vehicles still in stock. For vehicles which have already been delivered, customers must be contacted by phone to upgrade all vehicles.

OPERATING CYCLE

Turn the ignition key to the STOP position.

With reference to the Service Manual:

- Disconnect the negative battery terminal.
- Working in the engine compartment, replace the engine management control unit as described in Op. 1060G80.
- Perform the configuration of the new control unit.

Disposal of removed parts:

Removed part return required:

Local scrapping with TZM certification